WO 2005/060147 PCT/IB2004/052607




FIG.1




FIG.2

WO 2005/060147 PCT/IB2004/052607






FIG.3







$$g_2(x) = p_4^{-1} \circ f_2 \circ p_3(x) = (\frac{x}{3} + 3)^2$$
  
 $h_2(x) = p_3^{-1} \circ p_2(x) = 3 \bullet p_2(x)$ 

$$p_3(x) = \frac{x}{3} ; p_3^{-1}(x) = 3x \qquad h_2(x) = p_3^{-1} \circ p_2(x) = 3 \bullet p_2(x)$$

$$f_2(x) = x + 3 \qquad h_3(x) = p_5^{-1} \circ p_4(x) = p_5^{-1}(\sqrt{x})$$





 $p_4(x) = \sqrt{x}$ ;  $p_4^{-1}(x) = x^2$ 





FIG.6






FIG.8

WO 2005/060147 PCT/IB2004/052607




FIG.9